

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-373/93006(DRSS); 50-374/93006(DRSS)

Dockets No. 50-373; 50-374

Licenses No. NPF-11; NPF-18

Licensee: Commonwealth Edison Company
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Facility Name: LaSalle County Station, Units 1 and 2

Inspection Dates: January 25-29, 1993

Type of Inspection: Announced Physical Security

Date of Previous Physical Security Inspection: August 24-28, 1992

Inspector: James R. Kniceley
James R. Kniceley
Physical Security Inspector

2/17/93
Date

Approved By: James R. Creed
James R. Creed, Chief
Safeguards Section

2/17/93
Date

Inspection Summary

Inspection on January 25-29, 1993 (Reports No. 50-373/93006(DRSS);
No. 50-374/93006(DRSS))

Areas Inspected: Routine, announced physical security inspection involving Management Support; Protected and Vital Area Barriers; Detection and Assessment Aids; Access Control-Personnel, Packages, and Vehicles; Alarm Stations and Communications; Power Supply; Testing, Maintenance and Compensatory Measures; Training and Qualifications; and a review of a concern regarding implementation of 10 CFR 73.56 (Access Authorization Rule).

Results: The licensee was found to be in compliance with NRC requirements within the areas examined.

We have concluded that the security program is well implemented and is well managed. Licensee management attention and involvement in the security program are good. Resources are ample and reasonably allocated. The Training and Qualification program is effective and met regulatory requirements. Security personnel observed and interviewed were knowledgeable of their duties and responsibilities. The professionalism, attitude, appearance and performance of the security organization continues to be excellent. The housekeeping practices of security occupied areas was good. The removal of

9302240184 930217
PDR ADOCK 05000373
Q PDR

ENCLOSURE CONTAINS
10 CFR 2.790 INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

trailers from within the protected area greatly enhanced assessment and response capabilities.

The concern regarding the licensee's implementation of the Access Authorization Rule (10 CFR 73.56) was not substantiated (AMS No. RII'-92-A-0140).