

~~SAFEGUARDS INFORMATION~~

JUL 10 1985

Docket No. 50-315

Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the special safeguards inspection conducted by Mr. T. J. Madeda of this office on June 18 and 19, 1985, of activities at the Donald C. Cook Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. Smith, Jr., and other members of your staff at the conclusion of the inspection.

The special inspection was conducted regarding licensee failure to control access to vital areas and reporting of such failure to the NRC. The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements. You will be notified by separate correspondence of our decision regarding enforcement actions based on the findings of this inspection. No written response is required until you are notified of the proposed enforcement action.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 73.21(c)(2) of the NRC's "Rules of Practice," Part 73, Title 10, Code of Federal Regulations. This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, our report of this inspection will not be placed in the Public Document Room.

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

8507150192 850710
PDR ADOCK 05000315
G PDR

DMB
IE04
11

~~SAFEGUARDS INFORMATION~~

~~SAFEGUARDS INFORMATION~~

American Electric Power Service
Corporation

2

JUL 10 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

J. A. Hind
J. A. Hind, Director
Division of Radiation Safety
and Safeguards

Enclosure: Inspection Report
No. 50-315/85018(DRSS);
No. 50-316/85019(DRSS)
(UNCLASSIFIED SAFEGUARDS INFORMATION)

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
IE File
IE/DQADIP/ORPB
IE/ES
MNSS/SGPL
NRR/DL/SSPB
ACRS

cc w/enclosure, w/o UNCLASSIFIED
SAFEGUARDS INFORMATION:
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

RIII

Mada
Mada/jp
07/09/85

RIII

Creed
Creed

RIII

Axel
Axelson
7/9/85

RIII

Schultz
Schultz

RIII

Stanley
Stanley

RIII

Hind
Hind
#0

RIII

Day
Day

RIII

Kepler
Kepler

~~SAFEGUARDS INFORMATION~~