



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

APR 01 1985

Report Nos. 50-259/85-16, 50-260/85-16 and 50-296/85-16

Licensee: Tennessee Valley Authority
500A Chestnut Street, Tower II
Chattanooga, TN 37401

Docket Nos. 50-259, 50-260 and 50-296

License Nos. DPR-33, -52 and -68

Facility Name: Browns Ferry Units 1, 2 and 3

Inspection Date: March 11, 1985

Inspector:

William J. Tobin, for,
C. Patterson, Resident Inspector

3/26/85
Date Signed

Approved by:

D. R. McGuire, Chief, Physical Security Section
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

3/25/85
Date Signed

SUMMARY

Scope: During the conduct of routine inspections the Resident Inspector discovered that the guard posted at the Containment Drywell hatch could not control possible access.

Results: One violation was identified. (Access Control 85-16-01)

8506040645 850401
PDR ADOCK 05000259
Q PDR

SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.