




GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775
AREA CODE 504 635-6094 346-8651

May 16, 1985
RBG- 21003
File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Martin:

River Bend Station - Unit 1
Docket No. 50-458
Final Report/DR-279

Gulf States Utilities Company (GSU) has completed its evaluation of DR-279 concerning preventative maintenance (PM) for safety related equipment (e.g., LPCS and RCIC pumps, etc.). The PM required for the equipment was either scheduled but not performed or was unscheduled. Evaluation revealed that the equipment affected by this condition had not been compromised. Since the equipment will perform its intended safety function, GSU has determined this condition is not reportable under 10CFR50.55(e). However, the required PM has been scheduled to be performed.

Sincerely,

J. E. Booker

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

J PJD
JEB/PJD/amg

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

85-361

8506040714 850516
PDR ADOCK 05000458
S PDR

12-27
1/0