



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
URANIUM RECOVERY FIELD OFFICE  
BOX 25325  
DENVER, COLORADO 80225

FEB 16 1983

URFO:FWR  
Docket No. 40-8714  
04008714191E

In their December 27, 1982 letter to CCIC, the WDEQ indicates a number of deficiencies in the 1982 annual report on the Collins Draw ISL R&D project. The letter asks CCIC to provide answers relating to potentiometric water level data, water quality data at several wells, and monitor well responses to pumping. Submission of an annual report is not required by the NRC, however, data contained in the annual report is submitted in quarterly reports to the NRC which we reviewed in a timely manner. The NRC will continue to monitor all correspondence between the DEQ and CCIC and will take an active role as appropriate.

On January 20, 1983, CCIC submitted their responses to the DEQ concerning the deficiencies in the 1982 annual report. I have reviewed this document and find that it contains sufficient data to answer the DEQ's questions. No licensing or follow-up actions are necessary.

*Frederick W. Ross*

Frederick W. Ross, Project Manager  
Licensing Branch I  
Uranium Recovery Field Office  
Region IV

Case Closed: 04008714191E

9609190082 830216  
PDR ADOCK 04008714  
C PDR