

JUL 9 1985

Docket No. 50-409

Dairyland Power Cooperative
ATTN: Mr. F. W. Linder
General Manager
2615 East Avenue - South
La Crosse, WI 54601

Gentlemen:

This refers to the routine safety inspection conducted by Ms. P. R. Rescheske of this office on June 10-14, 1985, of activities at LaCrosse Boiling Water Reactor authorized by NRC Operating License No. DPR-45 and to the discussion of our findings with Mr. J. D. Parkyn and members of his staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief
Engineering Branch

Enclosure: Inspection
Report No. 50-409/85011(DRS)

cc w/enclosure:

J. Parkyn, Plant Superintendent
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
John J. Duffy, Chief
Boiler Section
Ness Flores, Chairperson
Wisconsin Public Service
Commission
Spark Burmaster, Coulee
Region Energy Coalition

8507150474 850709
PDR ADOCK 05000409
G PDR

RIII

Rescheske/cs
06/26/85

RIII

Ring

RIII

Boyd
7/9/85

RIII

Harrison
7/8

IE01 1/1