

JUL 08 1985

Docket No. 50-29

Yankee Atomic Electric Company
ATTN: Mr. L. H. Heider
Vice President of Operations
1671 Worcester Road
Framingham, Massachusetts 01701

Gentlemen:

Subject: Inspection Report Number 50-029/85-10

A routine safety inspection was conducted by Mr. Richard K. Struckmeyer of this office on May 28-31, 1985 at the Yankee Nuclear Power Station, Rowe, Massachusetts of the radiological environmental monitoring program. Areas that were reviewed included sample collection, control of contractor activities, meteorological monitoring, audits and reports.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:

Thomas T. Martin
Thomas T. Martin, Director
Division of Radiation Safety
and Safeguards

Enclosure: NRC Region I Inspection Report Number 50-029/85-10

cc w/encl:

N. N. St. Laurent, Plant Superintendent
J. E. Tribble, President
G. J. Papanic, Jr., Senior Project Engineer - Licensing
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Massachusetts (2)

OFFICIAL RECORD COPY

8507150529 850708
PDR ADOCK 05000029
PDR

11 IED6

bcc w/encl:

Region I Docket Room (with concurrences)

Senior Operations Officer (w/o encl)

DRP Section Chief

RI:DRSS
Struckmeyer/rw
6/26/85

for

RI:DRSS
Shanbaky
7/3/85

mtb
RI:DRSS
Bellamy
7/5/85

OFFICIAL RECORD COPY

IR YANKEE 85 10 - 0002.0.0
06/24/85