

JUL 23 1985

In Reply Refer To:  
Docket: 50-274/85-01

U.S. Department of Interior  
Geological Survey  
ATTN: Dr. Hugh T. Millard, Jr.  
Reactor Administrator  
P.O. Box 25046 - Mail Stop 424  
Denver Federal Center  
Denver, Colorado 80225

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. E. Hyder and Ms. A. E. Sanchez-Pope of the Los Alamos National Laboratory during the period June 10-13, 1985, of activities authorized by NRC Operating License R-113 and to the discussion of their findings with you and members of your staff at the conclusion of the inspection.

Areas examined during the inspection included organization, logs, and records; review and audits; requalification training; procedures; surveillance activities; experiments; fuel-handling activities; radiation control; radwaste management; emergency planning; physical security; and nuclear materials safeguards. These findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original Signed By  
E. H. Johnson

E. H. Johnson, Chief  
Reactor Project Branch

Enclosure:  
Appendix - NRC Inspection Report  
50-274/85-01

bcc:	
RPB	R. D. Martin, RA
Section Chief, RPB/C	MIS System
RSTS Operator	J. E. Hyder, LANL
RIV Official Reading File	A. E. Sanchez-Pope, LANL

RIV:RPB/C	RPB <i>EHJ</i>
GLConstable/lk	EHJohnson
7/18/85	7/23/85

8507290260 850723  
PDR ADOCK 05000274  
Q PDR

IE01  
11