

July 17, 1985

MEMORANDUM FOR: Ernie Rossi, Chief
Events Analysis Branch
Division of Emergency Preparedness
and Engineering Response

FROM: Gary G. Zech, Chief
Vendor Program Branch
Division of Quality Assurance, Vendor
and Technical Training Center Programs

SUBJECT: REQUEST FOR FOLLOWUP ON POTENTIALLY GENERIC PROBLEM
REGARDING LOOSE CRIMPED CONNECTIONS OBSERVED AT
CLINTON BATTERY CHARGERS MANUFACTURED BY POWER
CONVERSION PRODUCTS, CRYSTAL LAKE, ILLINOIS

Reference: Region III Action Item 84-379 DEPER Potentially
Generic Item 84-36, 10 CFR Part 21 Item 85-146

The enclosed report 99900741/85-01 documents the results of an inspection conducted at Power Conversion Products (PCP) on May 22 and 23, 1985, and addresses the potentially generic item regarding the loose crimped connections reported in Region III Morning Report dated October 19, 1984. We do not consider this item to be generic.

original signed by:
J.C. Stone

[Signature] Gary G. Zech, Chief
Vendor Program Branch
Division of Quality Assurance, Vendor
and Technical Training Center Programs

Enclosure:
Report 99900741/85-01

DISTRIBUTION: w/o enclosure
DMB:IE:09 (99900741/85-01)
VPB Reading
DQAVT Reading
EMerschhoff
KNaidu

[Signature]
VPB:DQAVT
KNaidu:sam
8/3/85

[Signature]
SO/VPB:DQAVT
EMerschhoff
8/3/85

[Signature]
BC/VPB:DQAVT
GGZech
8/10/85

8507290337 850717
PDR QA999 EMVPOWER
99900741 PDR

IE09
1/0