

6/12/85
4:00 PM

PDR

gtr

29

75227346

EQUIPMENT FREEZE

The following list of items ^{is} ~~if~~ the licensee's proposal for continued quarantine:

1. MFP's Turbine and Controls
2. SFRCS and associated instrument channels
3. AuxFeed Pump Turbines and Controls
4. MSIVs including controls - Actuating Circuits, Pneumatic supplies
5. S/U Feed Valve SP-7A - and controls
6. Source Range instrument channels
7. Turbine Bypass Valve SP-13A2 - Any other components for which there is found an indication of water hammer damage
8. PORV & Controls and Actuation system
9. Main Steam Safety valves
10. AF 599 & 608 valves, Actuators and Controls

This item was released by the Fact-Finding Team:

1. SPDS

This item was added by the Fact-Finding Team:

1. SW Valve and Controls on AFW alternate supply

It is agreed that no work will be done in the proximity of, or on, this equipment.

The licensee agreed to complete a walkdown of the Main Steam System by appropriate personnel to identify any additional damage that may have been caused by water hammer.

The Fact-Finding Team stated that:

- (a) If required for safety, work shall proceed.
- (b) Surveillance Requirements of the Technical Specifications should be satisfied.
- (c) The team should be advised of any actions taken in the two areas above.

8507300059 850612
PDR ADOCK 05000346
P PDR

(21)

6/13
TF POR

EQUIPMENT FREEZE

The following list of items is the licensee's proposal for continued quarantine: /

1. MFP's Turbine and Controls
2. SFRCS
3. AuxFPumps Turbine and Controls
4. MSIV's Controls - Actuating Circuits
5. SUFP Valve SP-7A - and controls
6. Source Range Detectors
7. Turbine Bypass Valve SP-13A2 - Any other indication of water hammer damage
8. PORV & Controls and Actuation system
9. MSS
10. AF 599 & 608 Actuators and Controls
11. SPDS Team cancelled

This item was added on by the Fact Finding Team:

1. SW Valve and Controls on AFW alternate supply

It is understood that no work will be done in the proximity of, or on this equipment.