

APPENDIX A

NOTICE OF VIOLATION

Northeast Nuclear Energy Company
Millstone Nuclear Power Station, Unit 3

Docket No. 50-423
License No. CPPR-113

During inspection from May 20 - June 14, 1985, and in accordance with 10 CFR 2, Appendix C, the following violation was identified:

10 CFR 50, Appendix B, Criterion V and the Northeast Nuclear Energy Company Startup Test Manual require that activities affecting quality be accomplished in accordance with procedures.

Contrary to the above, on May 30, 1985, an activity affecting quality was not accomplished in accordance with procedures, in that Fire Protection Water valve, FPW-V555, was not red-tagged shut for system flushing as required by Phase I Test Procedure T3341A1F02, resulting in partial flooding of the Service and Control Buildings.

This is a Severity Level IV Violation (Supplement II).

Pursuant to 10 CFR 2.201, Northeast Nuclear Energy Company is required to submit to this office, within thirty days of the date of the letter transmitting this Notice, a written reply including: (1) corrective steps taken and results achieved; (2) corrective steps to be taken; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

The responses directed by this Notice are not subject to the Office of Management and Budget clearance procedures otherwise required by the Paperwork Reduction Act of 1980, PL 96-511.

B507160558 B50708
PDR ADOCK 05000423
G PDR