

FILE COPY

MAR 18 1985

MAGNA CHEK, Inc.
ATTN: David Cardwell
2125 Riggs
Warren, MI 48091

SUBJECT: REQUEST FOR AN AMENDMENT TO LICENSE NUMBER 21-19111-02 DATED
DECEMBER 13, 1984 AND OUR REQUEST FOR ADDITIONAL INFORMATION BY PHONE
ON JANUARY 22, 1985

Gentlemen:

We requested in the above mentioned phone conversation between David Cardwell and John Madera of our office that you respond to us with additional information. We requested the names, duties and qualifications of the individuals responsible for your training program; your procedures for training previously trained individuals; procedures for control access to the roof area of your exposure room; and the name, qualifications and experience of the individual responsible for the actual retrieval of a lost or disconnected source.

A check of our files indicate that we have not received a response from you to date. You are hereby notified that you have 30 days in which to submit a response to this notice.

Upon failure to file an answer within the specified time, we will consider your request abandoned and will void this action. This is without prejudice to resubmission of the application.

Please respond in duplicate and refer to Control Number 77973.

Sincerely,

Original Signed By
Bruce S. Mallett, Ph.D., Chief
Materials Licensing Section

RIII

Mallett/cm
03/14/85

8506060315 850522
REG3 LIC30
21-19111-02 PDR

CONVERSATION RECORD

TIME

9:30 @

DATE

1/22/85

TYPE

☐ VISIT

☐ CONFERENCE

☒ TELEPHONE

☐ INCOMING

☒ OUTGOING

ROUTING

NAME/SYMBOL

INT

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

David Cardwell

ORGANIZATION (Office, dept., bureau, etc.)

Magna Chek, Inc.

TELEPHONE NO.

313/756-4070

SUBJECT

Telephone Deficiency

SUMMARY

① Submit the names & duties & Qualifications of the individuals responsible for the program. (RSO, Asst. etc.)

② Submit the names of the individuals, Qualifications etc. that are responsible for the training program (should have Radiographer training).

③ Submit procedures for training previously trained individuals: CP & Emer. procedures; use of equip.; spam.

④ Submit procedure for control access to roof area (High Radiation) & surveillance.

⑤ Submit Qualifications and experience of person retrieving lost or disconnected source: General procedure for recovery.

ACTION REQUIRED

Ltr. from licensee with application and new manuals.

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

DATE

JR-Mader

1/22/84

ACTION TAKEN

SIGNATURE

TITLE

DATE



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAR 18 1985

MAGNA CHEK, Inc.
ATTN: David Cardwell
2125 Riggs
Warren, MI 48091

SUBJECT: REQUEST FOR AN AMENDMENT TO LICENSE NUMBER 21-19111-02 DATED
DECEMBER 13, 1984 AND OUR REQUEST FOR ADDITIONAL INFORMATION BY PHONE
ON JANUARY 22, 1985

Gentlemen:

We requested in the above mentioned phone conversation between David Cardwell and John Madera of our office that you respond to us with additional information. We requested the names, duties and qualifications of the individuals responsible for your training program; your procedures for training previously trained individuals; procedures for control access to the roof area of your exposure room; and the name, qualifications and experience of the individual responsible for the actual retrieval of a lost or disconnected source.

A check of our files indicate that we have not received a response from you to date. You are hereby notified that you have 30 days in which to submit a response to this notice.

Upon failure to file an answer within the specified time, we will consider your request abandoned and will void this action. This is without prejudice to resubmission of the application.

Please respond in duplicate and refer to Control Number 77973.

Sincerely,

for Patricia Vachon
Bruce S. Mallett, Ph.D., Chief
Materials Licensing Section