



MIDDLE SOUTH  
UTILITIES SYSTEM

**LOUISIANA**  
POWER & LIGHT

142 DELARONDE STREET  
NEW ORLEANS, LOUISIANA


• P.O. BOX 8008  
70174-8008

• (504) 388-2345

May 29, 1985

W3P85-1400  
A4.05

Mr. Robert D. Martin  
Regional Administrator, Region IV  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011



Dear Mr. Martin:

Subject: Waterford 3 SES  
Docket No. 50-382  
Facility Operating License No. NPF-38  
POTENTIALLY REPORTABLE DEFICIENCY NO. 180  
"Failure to Maintain Adequate Document Control of  
Vendor Manuals"  
Extension of Report Schedule

- References: 1. W3P85-1240 from K.W. Cook (LP&L) to R.D. Martin (NRC),  
dated 4/29/85.
2. W3P84-2386 from K.W. Cook (LP&L) to J.T. Collins (NRC),  
dated 9/13/84

In accordance with 10CFR50.55(e), LP&L provided telephone notification on September 18, 1984 of the subject deficiency. Reference 1 requested an extension for the submittal of a written report on PRD-180 to April 30, 1985. Reference 2 provided LP&L's response to related Violation 8425-01 which specified details on corrective actions planned and underway to resolve this violation.

LP&L requires additional time to evaluate the safety significance of PRD-180 for reportability determination of the deficiency per 10CFR50.55(e) guidance. LP&L has, therefore, rescheduled the submittal of the written report on PRD-180 for July 1, 1985.

Very truly yours,

K.W. Cook  
Nuclear Support & Licensing Manager

KWC:GEW:sms

cc: NRC, Director, Office of I&E  
G.W. Knighton, NRC-NRR  
D.M. Crutchfield, NRC-NRR  
NRC Resident Inspectors Office  
INPO Records Center (J.T. Wheelock)  
E.L. Blake  
W.M. Stevenson

85-392

8506060573 850529  
PDR ADOCK 05000382  
S PDR

IE-27

1/0