

40-8768

SEQUOYAH FUELS CORPORATION



POST OFFICE BOX 25861 • OKLAHOMA CITY, OKLAHOMA 73125

RETURN TO ~~SEQUOYAH FUELS CORPORATION~~, PDR

May 10, 1985

Mr. Ed Hawkins, Chief
 Licensing Branch 1
 Uranium Recovery Field Office
 Nuclear Regulatory Commission
 P. O. Box 25325
 Denver, Colorado 80225-0325

ATTN: Paul Hildenbrand



RE: Docket 40-8768 (SUA-1387)
 Evaporation Pond Leak
 Final Report

Dear Mr. Hildenbrand:

On December 26, 1984, a leak in the west cell of the evaporation pond was reported to your office. As stated in the April 3, 1985 status report on the referenced leak, a small tear in the west cell liner was located and repaired in late March. During April the liner was tested to a water level of six feet deep and that portion of the liner above the water level was tested with a water spray system. No additional leaks have been found or indicated; therefore, this cell is being returned to normal service.

If there are any questions in regard to the liner repairs or testing procedures, please call me (405/270-2972).

Sincerely,

M. D. Freeman
 M. D. Freeman, Director
 Chemical Mining

MDF/jlm

xc: J. Stauter
 E. Orrell/C. Fletcher
 R. Spears

DESIGNATED ORIGINAL

Certified By

Mary C. Hood

8506060610 850510
 PDR ADCK 04008768
 C PDR

FEE EXEMPT

00606

A SUBSIDIARY OF KERR-MCGEE CORPORATION