

DmB



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

JUN 28 1985

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Richard P. Crouse
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. W. Rogers and D. Kosloff of this office on May 14 through June 10, 1985, of activities at Davis-Besse Nuclear Power Station authorized by NRC Operating License No. NPF-3 and to the discussions of our findings with Mr. S. Quennoz at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosure will be placed in the NRC's Public Document Room.

8507170479 850628
PDR ADOCK 05000344
G PDR

11
IEOI

Toledo Edison Company

2

JUN 28 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W.D. Shafer"

W. D. Shafer
Reactor Projects Branch 2

Enclosure:
Inspection Report
No. 50-346/85020(DRP)

cc w/enclosure:
S. Quennoz, Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert H. Quillin, Ohio
Department of Health

RIII

Jackiw/rr
06/28/85

RIII

Shafer