

May 16, 1985

Docket Nos. 50-266
and 50-301

Mr. C. W. Fay, Vice President
Nuclear Power Department
Wisconsin Electric Power Company
231 West Michigan Street Room 308
Milwaukee, Wisconsin 53201

Dear Mr. Fay:

SUBJECT: GENERIC LETTER 83-28 ITEMS 4.2.1 AND 4.2.2 - PREVENTATIVE
MAINTENANCE PROGRAM FOR REACTOR TRIP BREAKERS/MAINTENANCE
AND TRENDING (MPA B-81)

The staff has reviewed your responses of November 7, 1983 and December 28, 1984 on the subject items. Based on our review, the staff finds that your program for preventative maintenance of the reactor trip breakers at Point Beach Units 1 and 2 is acceptable provided your maintenance interval does not exceed 12 months and your current practices with regard to measurement of undervoltage trip attachment dropout voltage, trip force, breaker response time and breaker insulation resistance are maintained. The details of our review are contained in the enclosed Safety Evaluation. Should you have any questions, please contact your NRC project manager, T. G. Colburn, at (301) 492-4709.

Sincerely,

Original signed by:

James R. Miller, Chief
Operating Reactors Branch #3
Division of Licensing

Enclosure:
Safety Evaluation

cc w/enclosure
See next page

8506070654 850516
PDR ADOCK 05000266
P PDR

ORB#3:DL
PKreutzer
5/16/85

ORB#3:DL
TColburn:dd
5/9/85

EQB
VNoonan
5/14/85

ORB#3:DL
JRMiller
5/15/85