



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30303

*J. A. Olshinski*  
*Carlin*  
*Hunt*  
*inf*

APR 10 1984

MEMORANDUM FOR: Uldis Potapovs, Chief, Vendor Program Branch  
Division of Vendor and Technical Programs, RIV

FROM: Richard C. Lewis, Director, Division of Project and  
Resident Programs

SUBJECT: CONSTRUCTION DEFICIENCY REPORT - CONFIRMATION OF TELECON  
(AITS NO. F02700443 )

Enclosed is a 10 CFR 50.55(e)/10 CFR 21 report received from Carolina  
Power and Light Co . This appears to be a generic problem. Would you please  
follow up on the generic aspects of the problem with the AE/Vendor? Should you  
have additional questions, we will be glad to discuss them with you.

*R.C. Lewis*  
Richard C. Lewis

Enclosure:  
10 CFR 50.55(e)/10 CFR 21 Report

cc w/encl:

R. W. Starostecki, DPRP, RI  
✓ J. A. Olshinski, DEOP, RII  
C. E. Norelius, DPRP, RIII  
R. P. Denise, DRRP&EP, RIV  
T. W. Bishop, DRRPEI, RV  
G. G. Zech, DQASIP, IE  
C. J. Heltemes, AEOD

CONTACT:  
A. Hardin  
(242-5509 )

8506100022 850117  
PDR FOIA  
BELL84-886 PDR

## MORNING REPORT - REGION II

DATE: Ap. 9, 1984

LICENSEE/FACILITY

HARRIS UNIT 1

: 50-400

NOTIFICATION/SUBJECT

9:45 4/6

DESCRIPTION OF ITEM OR EVENT*Potential 50.55c and Part 21 -*  
TURBOCHARGER DEFICIENCY TRANS AMERICAN DELAVAL :

*small* → The licensee ~~has received~~<sup>ed</sup> a report of a potential deficiency of insufficient lubrication<sup>of</sup> of the thrust bearings on the turbochargers for the Trans-American Delaval diesel generators.

There are four DGS at the Harris site which could be affected.

*(Previously)*  
~~This potential 50.55c was reported to the NRC on February 15, 1984~~ *4/15/84*

as a Part 21 Report. The licensee is evaluating the potential defect. Region IV notified. Routine Followup.

## DISTRIBUTION:

Regional Administrator (original)

J. A. Olshinski

DPRP File (2)

Originator A. K. Hardin

## APPROVED BY:

Originator AKH

Section Chief

Branch Chief RLR. C. Lewis RL