

DMB

Wayne H. Jens
Vice President
Nuclear Operations

~~SAFEGUARDS INFORMATION~~

Detroit
Edison

Fermi-2
6400 North Dixie Highway
Newport, Michigan 48166
(313) 586-4150

July 3, 1985
NE-85-0398

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reference: Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-33

Subject: Detroit Edison Response
Inspection Report 50-341/85023

This letter responds to the item of noncompliance described in your Inspection Report No. 50-341/85023. This inspection was conducted by Mr. J. L. Belanger of NRC Region III on May 1 and 2, 1985.

The item of noncompliance is discussed in this reply as required by Section 2.201 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations.

We trust this letter satisfactorily responds to the non-compliance cited in the inspection report. If you have questions regarding this matter, please contact Mr. Lewis Bregni, (313) 586-5083.

Sincerely,

Wayne H Jens

cc: (*with attachment)
P. M. Byron*
N. J. Chrissotimos
J. R. Creed*
USNRC, Document Control Desk
Washington, D.C. 20555

IEOH

8507230355 850703
PDR ADOCK 05000341
G PDR

~~SAFEGUARDS INFORMATION~~

10

WHEN SEPARATED FROM ENCLOSURES, HANDLE THIS DOCUMENT AS
DECONTROLLED.