


B & B PERFORATORS
P. O. BOX 787
UPTON, WYOMING 82730

ms-16
T1
3d-28656

June 10, 1985



U. S. Nuclear Regulatory Commission - Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Attn: Mr. Jack E. Whitten
Nuclear Materials Safety Section

RE: Pending License Application - Control No. 460611

Dear Mr. Whitten:

Your letter of May 23, 1985, requested additional information and clarification in order to complete your review of our byproduct material license application. We respond as follows:

1. Please reference Figure #1 in the back of our Operating and Emergency Procedures. This form will be used to conduct inspection and maintenance as required. This inventory is referenced in Section VII-A of our procedures. As Radiation Protection Officer I will see that the inspections are made and recorded at intervals not to exceed six months, and will maintain the inventory/inspection records for a period of two years for inspection by the NRC.
2. The following documents and records will be available at temporary job sites: (a) Operating and Emergency Procedures; (b) Survey records for the period of operation at the temporary job site; (c) Evidence of current calibration for the radiation survey instruments in use at the temporary job site; and (d) a copy of our NRC license, if operating in an Agreement State under reciprocity.
3. Lost source retrieval and abandonment procedures are outlined in our Operating and Emergency Procedures, Section V. Paragraph A of Section V states that a written agreement with the well owner/operator will be executed prior to performing well logging operations.

We trust this information will allow you to complete your review of our application and issue the license at an early date.

Sincerely,


Craig E. Bullard
Radiation Protection Officer

pm
cc: Keith Moon - SC&A Inc.

8507240331 850625
REG4 LIC30
49-23177-01 PDR

460611

B & B PERFORATORS
P. O. BOX 787
UPTON, WYOMING 82730

June 10, 1985

U. S. Nuclear Regulatory Commission - Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Attn: Mr. Jack E. Whitten
Nuclear Materials Safety Section

RE: Pending License Application - Control No. 460611

Dear Mr. Whitten:

Your letter of May 23, 1985, requested additional information and clarification in order to complete your review of our byproduct material license application. We respond as follows:

1. Please reference Figure #1 in the back of our Operating and Emergency Procedures. This form will be used to conduct inspection and maintenance as required. This inventory is referenced in Section VII-A of our procedures. As Radiation Protection Officer I will see that the inspections are made and recorded at intervals not to exceed six months, and will maintain the inventory/inspection records for a period of two years for inspection by the NRC.
2. The following documents and records will be available at temporary job sites: (a) Operating and Emergency Procedures; (b) Survey records for the period of operation at the temporary job site; (c) Evidence of current calibration for the radiation survey instruments in use at the temporary job site; and (d) a copy of our NRC license, if operating in an Agreement State under reciprocity.
3. Lost source retrieval and abandonment procedures are outlined in our Operating and Emergency Procedures, Section V. Paragraph A of Section V states that a written agreement with the well owner/operator will be executed prior to performing well logging operations.

We trust this information will allow you to complete your review of our application and issue the license at an early date.

Sincerely,



Craig E. Bullard
Radiation Protection Officer

pm
cc: Keith Moon - SC&A Inc.