



Log # TXX-96514
File # 10200
Ref. # 10CFR50.73(a)(2)(i)(B)

December 10, 1996

C. Lance Terry
Group Vice President

U. S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
CONDITION OUTSIDE OF DESIGN BASIS
LICENSEE EVENT REPORT 445/96-009-00

Enclosed is Licensee Event Report (LER) 96-009-00 for Comanche Peak Steam Electric Station Units 1 and 2. "The 480v Switchgear Breakers Racked Out in the Cubicle in the Remove Position Resulting in a Seismically Unqualified Condition Outside the Design Basis."

The condition described in the enclosed LER was identified on November 6, 1996, however it was not deemed reportable until November 12, 1996. TU Electric will provide additional information with respect to qualification of these breakers in a supplement to this LER. The estimated date for the aforementioned supplement is February 15, 1997.

Sincerely,

C. L. Terry
C. L. Terry

By: *Roger D. Walker*
Roger D. Walker
Regulatory Affairs Manager

OB:ob
Enclosure

cc: Mr. L. J. Callan, Region IV
Mr. J. I. Tapia, Region IV
Resident Inspectors, CPSES

9612170315 961210
PDR ADOCK 05000445
S PDR

160109