



**Northeast  
Utilities System**

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128  
Waterford, CT 06385-0128  
(203) 447-1791

December 13, 1996

Docket No. 50-245  
B16052

Re: 10CFR50.73(a)(2)(ii)

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555


This letter forwards Licensee Event Report (LER) 96-057-00 documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 1 on November 13, 1996. This LER is submitted pursuant to 10CFR50.73(a)(2)(ii).

The following are Northeast Nuclear Energy Company's (NNECO's) commitments made within this letter. All other statements made within this letter are for information only.

- B16052-1 The breakers which are racked down will be secured within the cubicle to prevent movement using existing hardware associated with the elevator mechanism by December 30, 1996. This immediate corrective measure will be reviewed to assess its suitability for a long term solution to the interaction concern.
- B16052-2 NNECO commits to address the seismic interaction issue and provide appropriate permanent physical and/or procedural changes to preclude this interaction of racked down breakers prior to declaring the 4kV system operable.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY



P. D. Hinnenkamp  
Director, Unit Operations

9612180068 961213  
PDR ADOCK 05000245  
S PDR

Attachment: LER 96-057-00

cc: H. J. Miller, Region I Administrator  
T. A. Easlick, Senior Resident Inspector, Millstone Unit No. 1  
J. W. Andersen, NRC Project Manager, Millstone Unit No. 1