



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

JAN 25 1979

MEMORANDUM FOR: D. B. Vassallo, Assistant Director for Light Water  
Reactors, Division of Project Management, NRR

FROM: G. W. Reinmuth, Assistant Director, Division of Reactor  
Construction Inspection, IE

SUBJECT: CLASSIFICATION OF SPENT FUEL POOL LINER PLATES  
(AITS F12193H1) (AITS F30382H1)

In the enclosed correspondence we are informing all regional offices that fuel pool liner plates are not required to be designed and erected to seismic category I requirements.

If you will concur in this correspondence we believe the transfer of lead responsibility serial number: IE:RCI:78-04 dated July 17, 1978 and the followup correspondence may be considered closed out.

Please call if you wish to discuss this subject further.


*G. W. Reinmuth*

G. W. Reinmuth  
Assistant Director  
Division of Reactor  
Construction Inspection  
Office of Inspection and Enforcement

Enclosure: Memo, GWReinmuth to  
RTCarlson, dated FEB 6 1979

cc: J. G. Davis, IE  
H. D. Thornburg, IE  
N. C. Moseley, IE  
B. H. Grier, RI  
J. P. O'Reilly, RII  
J. G. Keppler, RIII  
W. C. Seidle, RIV  
R. H. Engelken, RV

CONTACT: W. Laudan, IE  
49-27551



8501160571  
XA

1P.

A/6



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

Reg. 429 *Non destructive Exam of Cont. Vessel*  
Reg. 19 *Seismic Design Classification*  
Reg. 1,136  
JAN 25 1979

P-214  
*Frank Rinaldi*

ETI  
-28965

MEMORANDUM FOR: D. B. Vassallo, Assistant Director for Light Water Reactors, Division of Project Management, NRR

FROM: G. W. Reinmuth, Assistant Director, Division of Reactor Construction Inspection, IE

SUBJECT: CLASSIFICATION OF SPENT FUEL POOL LINER PLATES  
(AITS F12193H1) (AITS F30382H1)

In the enclosed correspondence we are informing all regional offices that fuel pool liner plates are not required to be designed and erected to seismic category I requirements.

If you will concur in this correspondence we believe the transfer of lead responsibility serial number: IE:RCI:78-04 dated July 17, 1978 and the followup correspondence may be considered closed out.


Please call if you wish to discuss this subject further.

*G. W. Reinmuth*  
G. W. Reinmuth  
Assistant Director  
Division of Reactor  
Construction Inspection  
Office of Inspection and Enforcement

Enclosure: Memo, GWReinmuth to  
RTCarlson, dated FEB 6 1979

cc: J. G. Davis, IE  
H. D. Thornburg, IE  
N. C. Moseley, IE  
B. H. Grier, RI  
J. P. O'Reilly, RII  
J. G. Keppler, RIII  
W. C. Seidle, RIV  
R. H. Engelken, RV

CONTACT: W. Laudan, IE  
49-27551  
29730



- structure - Cat I  
- Liner Plate with low leak chance  
- Applies to all Fuel Pools

8501160571 XA 2pp

*This is all inclusive*  
*Aggs. Discrepancies*  
*To Spent Fuel Pools*  
*Note: Feb 6 Memo*  
*Turn Your Answer to hold for*  
*2/27/79 Shao*  
*C.D. Thomas*



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

Reg. 429 *Non Destructive Exam of Cont. Welds*  
Reg. 19 *Seism - Design Classification*  
Reg. 1,136 *JAN 25 1979*

P-214  
Frank Rinaldi  
ETI  
28965

MEMORANDUM FOR: D. B. Vassallo, Assistant Director for Light Water Reactors, Division of Project Management, NRR

FROM: G. W. Reinmuth, Assistant Director, Division of Reactor Construction Inspection, IE

SUBJECT: CLASSIFICATION OF SPENT FUEL POOL LINER PLATES  
(AITS F12193H1) (AITS F30382H1)

In the enclosed correspondence we are informing all regional offices that fuel pool liner plates are not required to be designed and erected to seismic category I requirements.

If you will concur in this correspondence we believe the transfer of lead responsibility serial number: IE:RCI:78-04 dated July 17, 1978 and the followup correspondence may be considered closed out.


Please call if you wish to discuss this subject further.

*G. W. Reinmuth*  
G. W. Reinmuth  
Assistant Director  
Division of Reactor  
Construction Inspection  
Office of Inspection and Enforcement

Enclosure: Memo, GWReinmuth to  
RTCarlson, dated FEB 6 1979

cc: J. G. Davis, IE  
H. D. Thornburg, IE  
N. C. Moseley, IE  
B. H. Grier, RI  
J. P. O'Reilly, RII  
J. G. Keppler, RIII  
W. C. Seidle, RIV  
R. H. Engelken, RV

CONTACT: W. Laudan, IE  
49-27551  
29759



- structure Cat I
- Liner plate with low leak class
- Applies to all Fuel Pools

*15 This all inclusive  
does this eff  
To Spent fuel liner  
Note: Feb 6 Memo  
Return your answer  
to Larry Shao*

*To hold for  
D.D. Richards  
Thornburg*