



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

DMB COPY

030-17157

Date July 10, 1985

REF: Facility Syncor International Corp.

Inspection Report No(s). _____

OR License No(s). 21-19219-01MD

Thank you for your letter dated July 1, 1985,
informing us of the steps you have taken to correct the non-
compliance which we brought to your attention in our letter
dated June 20, 1985. We will examine these matters during
a future inspection.

RD
Douglas
07/10/85

SS
Simmons

SS
Sreniowski

8507310240 850710
REG3 LIC30
21-19219-01MD PDR

IE07