



PECO NUCLEAR

A Unit of PECO Energy

Thomas N. Mitchell
Vice President
Peach Bottom Atomic Power Station

PECO Energy Company
1848 Lay Road
Delta, PA 17314-9032
717 456 4000
Fax 717 456 4243

December 20, 1996

Docket Nos.: 50-277

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Mail Station P1-137
Washington, DC 20555

Subject: Peach Bottom Atomic Power Station
Unit 2 - Inservice Inspection

Gentlemen:

In accordance with the PECO Energy Company Second Ten-Year Interval Inservice Inspection Program, inservice inspections (ISIs) were completed on Unit 2 during the September 13, 1996 through October 3, 1996, eleventh refuel outage.

Enclosed are the "Summary Report for the October 22, 1994 to October 3, 1996 Periodic Inspection" (NIS-1) and the "Summary of ASME Repair and Replacement Completed." This submittal is required per paragraph IWA-6230 of the ASME Code Section XI, "Rules for Inservice Inspection of Nuclear Power Plant Components."

Sincerely,

Thomas N. Mitchell
Vice President,
Peach Bottom Atomic Power Station

TNM/MEW/GLS/RES:tjb

Mew GLS RES
Enclosures

cc: B. W. Gorman, Public Service Electric & Gas (w/o enclosures)
R. R. Janati, Commonwealth of Pennsylvania (w/o enclosures)
R. I. McLean, State of Maryland (w/o enclosures)
H. J. Miller, Administrator, Region I, USNRC
W. L. Schmidt, USNRC Senior Resident Inspector, PBAPS
H. C. Schwemm, Atlantic Electric (w/o enclosures)
A. F. Kirby III, Delmarva Power (w/o enclosures)
A. Schiaffino, Hartford Steam Boiler
Chief Boiler Inspector, Commonwealth of Pennsylvania

A047
11

CCN 96-14091