

**Northeast
Utilities System**

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128
Waterford, CT 06385-0128
(203) 447-1791

December 19, 1996

Docket No. 50-245
B15998

Re: 10CFR50.73(a)(2)(ii)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards supplemental Licensee Event Report (LER) 95-008-02, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 1 on April 11, 1995. This LER is submitted pursuant to 10CFR50.73(a)(2)(ii).


This supplemental LER updates the information contained in the Corrective Action section. Also, additional information is included regarding the reactor feed pump runout protection system. Lastly, there are some editorial and administrative changes.

The following is Northeast Nuclear Energy Company's (NNECO's) commitment made within this letter. All other statements made within this letter are for information only.

B15998-1 NNECO will complete the integrated testing prior to startup for operating Cycle 16.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY



P. D. Hinnenkamp
Director, Unit Operations

Attachment: LER 95-008-02

cc: Dr. W. D. Travers, Director, Special Projects
H. J. Miller, Region I Administrator
S. Dembek, NRC Project Manager, Millstone Unit No. 1
T. A. Easlick, Senior Resident Inspector, Millstone Unit No. 1

JE221