

JUL 30 1985

Docket Nos. 50-443
50-444

Public Service of New Hampshire
ATTN: Mr. Robert J. Harrison
President and Chief Executive Officer
P. O. Box 330
Manchester, New Hampshire 03105

Gentlemen:

Subject: 50-443/85-17

This refers to the routine safety inspection conducted by Messrs. H. Wescott and R. Barkley of this office on May 27 - July 5, 1985 at the Seabrook Station Units 1 and 2, Seabrook, New Hampshire of activities authorized by NRC License No. CPPR-135 and to the discussions of our findings held by Mr. Wescott with Messrs. McDonald, Singleton and others of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:

Samuel J. Collins, Chief
Projects Branch No. 2
Division of Reactor Projects

Enclosure: NRC Region I Inspection Report 50-443/85-17

8508050197 850730
PDR ADOCK 05000443
G PDR

IE01

11

OFFICIAL RECORD COPY

IR SEABROOK 85-17 - 0001.0.0
07/12/85

JUL 30 1985

cc w/encl:

John DeVincentis, Director, Engineering and Licensing
William B. Derrickson, Senior Vice President
Warren Hall, Operational Services Supervisor
Donald E. Moody, Station Manager -Seabrook Station
Gerald F. McDonald, Construction QA Manger
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of New Hampshire

bcc w/encl:

RI Docket Room (with concurrences)
DRP Section Chief
Senior Operations Officer (w/o encls)

acc

RI:DRP
Cerne/ca
7/24/85

[Signature]
RI:DRP
Gallo
7/27/85

[Signature]
RI:DRP
Collins
7/27/85