

DRAFT 4  
7/10/84

WATERFORD OPEN ISSUE

Task: A-296, A-306a, A-306k, A-306l, A-306m

Reference No.: 4-84-A-06/177, 184a, 184k, 184l, 184m

Characterization: It is alleged that Tompkins-Beckwith (T-B) may have violated the ASME Code requirements by failing to visually examine the shop pipe welds for leaks during hydrostatic tests.

Initial Assessment of Significance: Potential ASME code violation.

Source:

Approach to Resolution:

1. Review requirement, codes, specifications, etc.
2. Obtain procedures, test records, etc.
3. Determine validity of allegation.

Status: Under review.

Review Lead: L. Shao (RWH)

Support:

A-296

- 2 -

Estimate Resources: 1 man - 2 days

Estimated Completion: April 19, 1984

CLOSURE:

Document Name:  
A-296

Requestor's ID:  
JOHNNIE

Author's Name:

Document Comments:

Proof + File