

Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-295

Docket No. 50-304

As a result of the inspection conducted on May 30 through July 1, 1985, and in accordance with the General Policy and Procedures for NRC Enforcement Actions (10 CFR Part 2, Appendix C), the following violation was identified:

10 CFR 50, Appendix B, Criteria V, states in part, "Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, of a type appropriate to the circumstances....."

Contrary to the above: Technical Staff Surveillance (TSS) 15.6.96.23-1, Appendix C, was inappropriate in that it did not contain instructions to return valve 1CC9499 to its normal operating status (CLOSED) as specified in the System Operating Instruction (SOI)-6. Failure to return this valve to its normal operating status resulted in lifting relief valve 1CC9428 and spilling approximately 6,000 gallons of component cooling water on the containment floor.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

JUL 30 1985

Dated _____

C. E. Norelius

C. E. Norelius, Director
Division of Reactor Projects