



**Commonwealth Edison**  
One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

DMB

July 15, 1985

Mr. James G. Keppler  
Regional Administrator  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

SUBJECT: Braidwood Station Units 1 and 2  
Supplemental Response to Inspection Reports Nos.  
50-456/85-015 and 50-457/85-016  
NRC Docket Nos. 50-456 and 50-457

REFERENCE (a): W. S. Little letter to Cordell Reed  
dated May 16, 1985.

(b): D. L. Farrar letter to James G. Keppler  
dated June 21, 1985.

Dear Mr. Keppler:

The enclosure to this letter supplements our Reference (b) response to the inspection conducted by Messrs. R. D. Schulz, W. J. Kropp and R. N. Gardner on March 25 through May 3, 1985 of activities at Braidwood Station as identified in Reference (a).

If you have any further questions on this matter, please direct them to this office.

Very truly yours,

8507220259 850715  
PDR ADOCK 05000456  
Q PDR

D. L. Farrar  
Director of Nuclear Licensing

/klj  
Enclosure

cc: NRC Resident Inspector - Braidwood

0371K

IE01  
1/1

JUL 16 1985

Supplemental Response to  
Inspection Report 456/85-015 and 457/85-016  
Item 456/85-015-06

In our Reference (b) response under Corrective Action Taken and Results Achieved the following statement was made.

"The NCR has been re-opened and a letter sent to Project Engineering requesting that the design status of all supports associated with NCR No. 600 be updated."

We wish to clarify this statement. NCR No. 600 was reopened on June 21, 1985. The letter to Project Engineering was transmitted on July 5, 1985.

0371K