



MAINE YANKEE ATOMIC POWER COMPANY •

EDISON DRIVE  
AUGUSTA, MAINE 04336  
(207) 623-3521

August 7, 1985  
MN-85-145

GDW-85-213

Director of Nuclear Reactor Regulation  
United States Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Mr. Edward J. Butcher, Jr.  
Acting Branch Chief  
Operating Reactors Branch No. 3  
Division of Licensing

References: (a) License No. DPR-36 (Docket No. 50-309)  
(b) USNRC Letter to MYAPCo. dated June 26, 1985

Subject: Schedule for Submitting Additional Information on Inadequate Core  
Cooling

Gentlemen:

In Reference (b), you transmitted a request for additional information on the Maine Yankee inadequate core cooling instrumentation system and requested that we provide a schedule for answering the questions. Subsequently, we met with members of your staff to discuss this topic.

As indicated at the meeting, we will exert our best effort to provide answers to the questions by August 30, 1985.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

G. D. Whittier, Manager  
Nuclear Engineering & Licensing

GDW/plb

cc: Dr. Thomas E. Murley  
Mr. Cornelius F. Holden

8508120439 850807  
PDR ADOCK 05000309  
P PDR

6214L-FWS

7002  
1/0