

RECEIVED
NRCVeterans
Administration

1985 MAY 23 PM 12: 23

May 20, 1985

REGION V IAF

In Reply Refer To: 644/114

Beth A. Riedlinger, Health Physicist
Nuclear Materials Safety Section
U.S. Nuclear Regulatory Commission, Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596

Dear Ms. Riedlinger:

In reply to your letter, Mail Control No. 16928, we submit the following information:

1. Our Radiation Protection Officer is Jay LeGrand, M.D.
2. Our survey instruments are calibrated by:

Radiation Safety Engineering, Inc.
7713 S. Butte Avenue
Tempe, Arizona 85284
Telephone (602) 897-9459
License #ARRA 7-192
3. The survey meter used to monitor is manufactured by: Dosimeter Corporation of America, Model 3700. Range of direction: 0.01 to 50 mr/hr, beta and gamma radiation.
4. Our bioassay procedure for personnel handling more than 0.1 millicurie of I-131 is to perform I-131 uptakes at 24 and 48 hours post handling of above materials. We do not use I-125 at the present time nor do we have a fume hood. However, scheduled remodeling of Nuclear Medicine Section will provide us with a fume hood that will meet stated requirements.

On our license renewal please delete Alexander Kovac, M.D. as he is no longer at this Medical Center.

Sincerely,

Ray L. Bourne
RAY L. BOURNE
Medical Center Director

B510240068 B50821
REG5 LIC30
02-10072-01 PDR