

SPRINGFIELD MEDICAL IMAGING CENTER

BALTIMORE PIKE & ANDREW ROAD, P.O. BOX 247 SPRINGFIELD, PA 19064

215/328-1068

MS 16
KO

Josephine Piccone, Ph.D.
Nuclear Materials Safety Section A
Division of Radiation Safety and Safeguards
U.S.N.R.C.
Region I
631 Park Ave.
King of Prussia, PA 19406

9-21-85

Dear Dr. Piccone,


With reference to your phone conversation with our consultant radiation physicist, Walter L. Robinson, and Control No. 104175, we wish to submit the following information in support of our application for a new byproduct material license.

First, we wish to drop our interest in licensure for a Gd-153 source for bone mineral analysis. We will amend our license in the future when we are sure which exact manufacturer we will be purchasing the dual photon absorptiometry equipment from.

Secondly, we confirm that we will follow the guidelines and commitments set forth in Appendices E & F in Regulatory Guide 10.8 (Oct. '80) for on-duty as well as off-duty deliveries.

Finally, since we anticipate initiation of nuclear medicine services to our patients by October 1, 1985, we would appreciate a phone call with the assigned N.R.C. License Number, at least, prior to that date. In this way we will be able to order our radiopharmaceuticals. We would appreciate our processed license by October 1, 1985; however, we realize there may be some difficulty in achieving this.

Sincerely,


Donald Kasper, M.D.
Springfield Medical Imaging

8510240327 850930
REG1 LIC30
37-20891-01 PDR

1985 SEP 25 PM 2:32

RECEIVED-REGION I

04175

"OFFICIAL RECORD COPY"

ML18

SEP 25 1985

9/17/85

TELEPHONE OR VERBAL CONVERSATION RECORD

TIME

6:00

☐ A.M.
☒ P.M.

☐ INCOMING CALL

☒ OUTGOING CALL

☐ VISIT

PERSON CALLING

Piccone

OFFICE/ADDRESS

NRC - Region I

PHONE NUMBER

EXTENSION

5169

PERSON CALLED Walter Robinson
for Springfield Med. Imaging
etc.

OFFICE/ADDRESS Baltimore Pike 4
Andrew Road, P.O. Box 247,
Springfield, PA 19064

PHONE NUMBER

EXTENSION

(717) 397-2569

CONVERSATION

SUBJECT

Response to deficiency letter not adequate.

SUMMARY

The following additional information is required: (1) The safe opening procedures for radioactive material using the radiopharmacy. (2) Device manufacturers for the bone mineral analyzers you wish authorization for. Also include the model numbers.

REFERRED TO:

ACTION REQUESTED

Response to the above in duplicate to mail etc # 104175

ACTION TAKEN

☐ ADVISE ME OF ACTION TAKEN.

INITIALS

J.M.F.

DATE

9/17/85

INITIALS

DATE

ML10

"OFFICIAL RECORD COPY"