

OCT 22 1985

Docket No. 50-306

Northern States Power Company
ATTN: Mr. C. E. Larson
Director of Nuclear
Generation
414 Nicollet Mall
Minneapolis, MN 55401

Gentlemen:

This refers to the routine safety inspection conducted by Mr. K. D. Ward of this office on September 16-18, and October 1, 1985, of activities at Prairie Island Nuclear Generating Plant, Unit 2, authorized by NRC Operating License No. DPR-60 and to the discussion of our findings with Mr. R. L. Dahlman at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief
Engineering Branch

Enclosure: Inspection Report
No. 50-306/85017(DRS)

cc w/enclosure:
E. L. Watzl, Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII Prairie
Island
Resident Inspector, RIII Monticello
John W. Ferman, Ph.D.,
Nuclear Engineer, MPCA

RIII
[Signature]
Ward/rr
10/21/85
10/21

RIII
[Signature]
Danielson
10/21

RIII
[Signature]
Burgess
10/22

RIII
[Signature]
Harrison
10/22

8510280385 851022
PDR ADCK 05000306
G PDR

201 11