



*The Service Difference™*

**Syncor International Corporation**

January 21, 1997

30-33224

U.S. Nuclear Regulatory Commission  
Attn.: Document Control Desk  
Washington, DC 20555

RE: Reply to a Notice of Violation, Syncor International Corporation, Chatsworth, CA  
(Bristol, PA) License No. 04-26507-01MD

To Whom It May Concern:

This letter is in response to the NRC's letter of December 23, 1996, regarding the inspection of Syncor's Bristol, PA, pharmacy, on October 23, 1996. Following is Syncor's response to the Notice of Violation:

1. This violation occurred because of a misunderstanding of the geometry requirements for syringes by the local Syncor staff. The misunderstanding was caused because of a change in the dose calibrator geometry procedures that occurred when Syncor consolidated its NRC licenses.

Syncor's Pharmacy Radiation Safety Officer (PRSO) believed that the dose calibrator geometry procedures from the NRC'S Guide for the Preparation of Applications for Nuclear Pharmacy Licenses (NPLG) were the procedures that Syncor had committed to follow. The NPLG procedures do not specifically call out the use of multiple syringes or volumes within syringes. The PRSO did not realize that there had been a modification to the procedures.

Syncor's consolidated license application contains dose calibrator geometry procedures which are different than those found in the NPLG. Syncor's new dose calibrator geometry procedures reference the use syringes of commonly used volumes. As mentioned above, the PRSO did not catch this change.

2. The corrective steps will consist of repeating the dose calibrator geometry test at this pharmacy using commonly used syringes and volumes within syringes. This additional geometry testing will be completed by January 31, 1997.
3. To avoid further violations of this nature, Syncor will inform all NRC PRSOs to verify their dose calibrator geometry testing has been carried out following the procedures contained in Syncor's consolidated license application.
4. Full compliance at the Bristol, PA, pharmacy will be achieved by January 31, 1997. Full compliance in all NRC pharmacies will be achieved by February 28, 1997.

Y/O  
Ied7


240024

20001 Prairie Street • Chatsworth, CA • 91311 • 818-886-7400

9701240176 970121  
PDR ADOCK 03033224  
C PDR

If I can be of any further assistance, please contact me at (818) 717-4551.

Sincerely,



David W. Pellicciarini  
Program Manager, Health Physics

cc: Robert Funari, President and CEO  
Jack Coffey, Vice President  
Brian Bender, Vice President  
Kathy Seifert, Corporate RSO  
Bob McClintock, Chief Auditor  
Pete van der Wal, General Manager  
Mike Mullin, Pharmacy Manager  
Wes Powers, Pharmacy RSO  
Regional Administrator  
U.S. Nuclear Regulatory Commission, Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-8064  
Ms. Linda Howell  
U.S. Nuclear Regulatory Commission, Region IV  
Division of Nuclear Material Safety  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-8064  
Mr. James Montgomery  
U.S. Nuclear Regulatory Commission, Region IV  
Walnut Creek Field Office  
Materials Branch  
1450 Maria Lane  
Walnut Creek, CA 94596-5368  
License File (NRC/97)