

RSB

OCT 28 1985

Docket No. 50-344

Portland General Electric Company  
121 S. W. Salmon Street  
Portland, OR 97204

Attention: Mr. Bart D. Withers  
Vice President, Nuclear

Gentlemen:

Thank you for your letter dated September 26, 1985, informing us of the steps you have taken to correct the items which we brought to your attention in our letter dated August 27, 1985. On the subject of Component Cooling Water (CCW) Safety Valve PSV-3323A testing, we request that you provide documentation on what repair actions were accomplished on valve PSV-3323B, what was found and evaluation notes to support the statement in your letter, that there was no reason to suspect a common mode failure. Your corrective actions will be verified during a future inspection.

Your cooperation with us is appreciated.

Sincerely,

Original signed by  
D. F. Kirsch

D. F. Kirsch, Acting Director  
Division of Reactor Safety and  
Projects

cc:  
W. Dixon, DOE

bcc:  
RSB/Document Control Desk (RIDS)  
Mr. J. Martin  
Mr. B. Faulkenberry  
G. Cook  
Resident Inspector

RV *JP*  
DPereira:dh  
10/15/85

*WJ*  
CClark  
10/18/85

*JD*  
RDodds  
10/18/85

*WJ*  
TYoung  
10/18/85

*an*  
AChaffee  
10/27/85

*K*  
DKirsch  
10/28/85

8511010170 851028  
PDR ADCK 05000344  
G PDR

11  
1E01