

AUG 12 1985

Mr. R. Wells, Chairman
Combustion Engineering Owners Group
Northeast Utilities Service Company
Post Office Box 270
Hartford, Connecticut 06101

Dear Mr. Wells:


SUBJECT: IE DRAFT BULLETIN: MOTOR-OPERATED VALVE FAILURES DURING PLANT
TRANSIENTS DUE TO IMPROPER SWITCH SETTINGS

The enclosed draft bulletin is being considered for issuance to all nuclear power reactor facilities holding an operating license or construction permit.

We would appreciate your comments on the draft bulletin and any input on the anticipated burden the bulletin may impose on nuclear utilities. Any comments received prior to August 23, 1985 will be considered in the preparation of the final draft to be presented to the Committee to Review Generic Requirements.

If you have any questions regarding this matter, please feel free to contact me or Mr. Henry Bailey of my staff. I can be reached at (301) 492-4193 and Henry at (301) 492-9006.

Sincerely,





Charles E. Rossi, Chief
Events Analysis Branch
Division of Emergency Preparedness
and Engineering Response
Office of Inspection and Enforcement

Enclosure: IE draft bulletin

Distribution:

✓ PDR
✓ OCS
DEPER R/F
EAB R/F
CRossi
RBaer
ELJordan
HBailey
RKiessel


EAB:DEPER:IE
HBailey:mj
8/9/85


EAB:DEPER:IE
CRossi
8/12/85

8508140487 850812
PDR I&E
MISC

PDR