

OCT 28 1985

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Joe Williams, Jr.
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by J. F. Norton of this office on October 8-10, 1985, of activities at Davis-Besse Nuclear Power Station authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. S. Wideman and others at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief
Engineering Branch

Enclosure: Inspection Report
No. 50-346/85032(DRS)

See Attached Distribution

8511040245 851028
PDR ADDCK 05000346
G PDR

IE01

OCT 28 1985

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of Ohio

Robert H. Quillin, Ohio

Department of Health

RIII
CCW
Norton/ld
10/28/85

RIII
Jackiw
Jackiw
10/28/85

RIII
ccw
Williams
10/28/85

RIII
JA
Harrison
10/28/85