


DMP

Medical Center  
(Atlanta)

1670 Clairmont Road  
Decatur GA 30033



85 OCT 22 A 9: 55

October 9, 1985

In Reply Refer To: 508/115

34-41358

Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W.  
Suite 3100  
Atlanta, GA 30303  
Attn: Mr. J. Philip Stohr, Director  
Division of Radiation Safety  
and Safeguards

RE: Notice of violation concerning license #10-01169-01/85-01

Package surveys were done on packages containing radioactive material received directly from suppliers, but Nuclear Pharmacy unit doses which are enclosed in individual lead containers and transported in metal boxes were monitored with survey meter. It was an oversight that complete survey on unit doses from Nuclear Pharmacy Inc. were not being done.

We now perform complete surveys on all packages received. These records are maintained in our hot lab. All technologists have been made aware of these procedures and new personnel will be informed also. Full compliance was achieved June 3, 1985.

As to the second violation on not maintaining complete records in the required units of measurements; this was also an oversight. Doses that were prepared in our hot lab with 99m Tc were stored approximately (56 half lives) 2 weeks before being surveyed and disposed. We used the words "Decayed Out" which we thought would be understood to mean activity below background instead of actual measurement in mR/hr. All technologists have been made aware of this procedure and all new personnel will be informed. Full compliance was achieved June 3, 1985.

Sincerely,

GLENN ALRED, JR.  
Medical Center Director

8511040289 851009  
REG2 LIC30  
10-01169-01 PDR

1/0  
IE07