

SIEMENS

January 21, 1997
RAC:97:004

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-001

Attention: Chief, Planning, Program, and Management Support Branch

Reference: EMF-97-007(P) and (NP), "SPC Guide Tube Compatibility with Westinghouse Reactor RCCAs," Siemens Power Corporation, January 1997.

Transmittal of EMF-97-007(P)

The referenced report was submitted to you on January 15, 1997. In the final review of that report, there were some typographical errors discovered. The corrections for these errors are:


- Page ii, Figure 6, listed as being on page 19, should be page 20.
- Page 1, second paragraph, "...significant guide tube distortion this conclusion..." should be "...significant guide tube distortion. This conclusion...."
- Figure 7 on page 21 should be replaced with attached Figure 7.

When you issue your review, we intend to incorporate your review evaluation, any additional correspondence, and the errata described in this letter as part of a later version of that report.

As in the original submittal, Siemens Power Corporation considers the information in Figure 7 to be proprietary. The affidavit enclosed with the original submittal satisfies the requirements of 10 CFR 2.790(b) to support the withholding of this information from public disclosure.

If you have any questions, or if I can be of further assistance, please call me at (509) 375-8290 or Don Curet at (509) 375-8563.

Very truly yours,


R. A. Copeland
Product Licensing

280083

/smg

Attachment

cc: Ms. M. Chatterton, USNRC (w/o Attachment)
Mr. E. Wang, USNRC
Mr. E. Weiss, USNRC (w/o Attachment)
Mr. H. D. Curet (SPC)

Siemens Power Corporation

Nuclear Division
Engineering & Manufacturing

2101 Horn Rapids Road
P.O. Box 130
Richland, WA 99352-0130

Tel: (509) 375-8100
Fax: (509) 375-8402

9701290087 970121
PDR TOPRP EMVEXXN
C PDR

T007%
RD-8-2
EXXON