

JUL 26 1985

Docket No. 030-05326

License No. 29-07262-01

United States Pipe and Foundry Company  
ATTN: Cavit Buyukmihci  
Manager, Quality Control  
East Pearl Street  
Burlington, New Jersey 08016

Gentlemen:

Subject: Inspection Report No. 030-05326/85-01

This refers to the routine, safety inspection conducted by John J. Miller of this office on June 6, 1985, of activities authorized by NRC License No. 29-07262-01 and to the discussions of our findings held by Mr. Miller with yourself and Joseph Kostrub of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Per our discussion at the exit interview, we understand that you will do the following prior to resuming radiographic operations in your radiography cell:

- (i) Remove the rope barricade from the high radiation area on the roof of your facility and replace it with a 3 strand barbed wire fence (approximately 3 feet tall);
- (ii) Replace the faded warning signs around the perimeter of your roof with new high radiation area signs per 10 CFR 20.203.
- (iii) Perform a complete survey of the unrestricted areas outside of the radiography cell and maintain the results on record.

If your intent differs from our understanding, please notify this office in writing.

Within the scope of this inspection, no violations were observed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

RETURN ORIGINAL TO  
REGION I

OFFICIAL RECORD COPY

DL US PIPE - 0001.0.0  
07/17/85

8508150493 850726  
REG1 LIC30  
29-07262-01 PDR

1E:07

1/0

United States Pipe and Foundry Company 2

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:  
Laurence F. Friedman, Ph.D.  
John E. Glenn, Ph.D, Chief  
Nuclear Materials Safety Section B,  
Division of Radiation Safety  
and Safeguards

cc:  
Public Document Room (PDR)  
Nuclear Safety Information Center (NSIC)  
State of New Jersey

bcc:  
Region I Docket Room (w/concurrences)  
Senior Operations Officer  
John J. Miller, DRSS

RI:DRSS  
J.Miller/djh

7/16/85

RI:DRSS

Glenn

7/24/85

OFFICIAL RECORD COPY

DL US PIPE - 0002.0.0  
07/17/85