


40-8752041E



May 15, 1984

Mr. Harry Pettengill
U.S. Nuclear Regulatory Commission
Uranium Recovery Field Office
P.O. Box 25325
Denver, Colorado 80225

Dear Mr. Pettengill;

This letter is in reference to our recent telephone conversation concerning restoration of the Lucky Boy property.

Our present plans are to modify the Lucky Boy plant to process silver ores from the Lucky Boy property and from the adjacent Pioneer property. The Lucky Boy operation was a small pilot operation which was never put into production. It should be a relatively simple task to restore and convert the facility to a precious metals operation.

It is suggested that we meet on the property within the next few weeks and make a field survey of restoration and modification needs. It is anticipated that after our visit to the site, it will require approximately 15 days to formulate restoration and modification plans.

OFFICIAL DOCKET COPY 01174

9609300014 840515
PDR ADOCK 04008752
C PDR

I am presently working on a geological field project near Payson, Arizona. My schedule is such, that it would be best for me if we can arrange to meet in approximately two or three weeks.

I can be reach by telephone at 602 473 2649 or at 474-6641 in Payson.

Sincerely,
Harold E. Lang, G.P., Ph.D.

T. Clary
P.O. Box 2513
Globe, Arizona 85502



U.S. Nuclear Regulatory Commission
Uranium Recovery Field Office
P.O. Box 25325
Denver, Colorado 80225

Attn:
Mr. Harry Pettengill