



Northeast  
Utilities System

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128  
Waterford, CT 06385-0128  
(203) 447-1791

February 3, 1997  
Docket No. 50-336  
B16198

Re: 10 CFR 50.73(a)(2)(i)

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555


This letter forwards Licensee Event Report (LER) 96-024-01, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on May 7, 1996. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i). This LER supplement provides information on additional discrepancies that have been identified during the performance of the corrective actions for this LER.

The following are NNECO's commitments made within this letter. All other statements made within this letter are for information only.

B16198-01: In the response to NOV 336/96-08-07 (NNECO Commitment No. B16076-2), Millstone Unit 2 committed to perform a review of Technical Specification surveillance procedures to ensure compliance with Technical Specification surveillance requirements as part of the Operational Readiness Plan. This review will encompass the RPS and ESAS response time surveillance procedures to ensure that the identified discrepancies are adequately resolved.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

  
\_\_\_\_\_  
J. A. Price

Director - Millstone Unit No. 2

cc: see page 2

9702050062 970203  
PDR ADOCK 05000336  
S PDR

IE221

Attachment: LER 96-024-01

cc: W. D. Travers, Director of Special Projects  
H. J. Miller, Region I Administrator  
D. P. Beaulieu, Senior Resident Inspector (Acting), Millstone Unit No. 2  
D. G. McDonald, Jr., NRC Project Manager, Millstone Unit No. 2