

APPENDIX A

NOTICE OF DEVIATION

Public Service Company of Colorado  
Fort St. Vrain Nuclear Generating Station

Docket: 50-267  
License: DPR-34

During an inspection of Fort St. Vrain maintenance, with specific focus on control rod refurbishment, conducted during the period May 28 - June 28, 1985, a deviation from a commitment was identified. This deviation involved the failure to afford the equivalent protection of an NFPA Class A, 4-hour minimum rated facility. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1985), the deviation is listed below:

Public Service Company of Colorado committed, in Section B.5.19.9, of the Updated FSAR, Revision 2, to ANSI N45.2.9-1974, Requirements for Collection, Storage, and Maintenance of Quality Assurance Records for Nuclear Power Plants. There were no exceptions noted in the FSAR to this commitment. Section 5.6 of ANSI N45.2.9-1974 states, in part, that records ". . . should be afforded the equivalent protection of an NFPA Class A, 4-hour minimum rated facility."

In deviation from the above, a fire door in the records center file room had label plate data identifying the door as 3-hour rated.  
(50-267/8516-01)

In accordance with Appendix C to 10 CFR Part 2, Public Service Company of Colorado is requested to provide within 30 days a written explanation or statement describing corrective steps taken (or planned), the results achieved, and the date when corrective action will be completed.

Dated at Arlington, Texas,  
this 13th day of August, 1985.

8508190322 850813  
PDR ADOCK 05000267  
Q PDR