

DMB COPY

AUG 02 1985

Joseph Safko, M.D.
838 Market St.
Zanesville, OH 43701

License No. 34-13165-01

Gentlemen:

This refers to the routine safety inspection conducted by Ms. C. Casey of this office between June 25, 1985 and July 10, 1985, of activities authorized by NRC Byproduct Material License No. 34-13165-01 and to the telephone discussion of our findings with you at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated May 5, 1982, regarding apparent items of noncompliance found during our March 17, 1982 inspection. We have no further questions regarding these matters.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. J. Sreniawski, Chief
Nuclear Materials Safety Section 2

Enclosure: Appendix,
Notice of Violation


cc w/enclosure:
DMB/Document Control Desk(RIDS)

3508190455 850802
REG3 LIC30
34-16165-01 PDR

RIII


Casey/pg
07/30/85

RIII


Sreniawski
8/2/85

IE07
11