

MATERIALS LICENSE
SUPPLEMENTARY SHEET

License Number

13-14807-01

Docket or Reference Number

030-08079

Amendment No. 07

301836

North American Wood Products, Inc.
d/b/a Swain Industries
P.O. Box 306
Seymour, IN 47274

In accordance with the letter dated October 17, 1996, License Number 13-14807-01 is hereby terminated.

TERMINATED

0/1

FOR THE U.S. NUCLEAR REGULATORY COMMISSION

Date

10/21/96

By

Michael F. Weber

Nuclear Materials Licensing Branch, Region III

010000

9611010124 961021
PDR ADOCK 03008079
C PDR

COPY

2^{ml}
30
SD

BETWEEN:

License Fee Management Branch, ARM
and
Regional Licensing Sections

(FOR LFMS USE)
INFORMATION FROM LTS

Program Code: 03120
Status Code: 0
Fee Category: 3P
Exp. Date: 20030630
Fee Comments:
Decom Fin Assur Req: N

S2
13

LICENSE FEE TRANSMITTAL

A. REGION

1. APPLICATION ATTACHED

Applicant/Licensee: NORTH AMERICAN WOOD PRODUCTS, INC.
Received Date: 960917
Docket No: 3008079
Control No.: 301836
License No.: 13-14807-01
Action Type: Termination

2. FEE ATTACHED

Amount: 0
Check No.: 0

3. COMMENTS

Signed
Date

D. Hersey
9-11-96

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered / ☒)

1. Fee Category and Amount: *3K*

2. Correct Fee Paid. Application may be processed for:

Amendment
Renewal
License

3. OTHER

Signed
Date

SC
9/24/96

1996 SEP 23 AM 11:21

SEP 30 1996

RECEIVED BY LFDCB

Date *Sept. 23, 1996*

Log *SEP 8 III*

By *SC*

Date Completed *9/24/96*

Seymour Particleboard Manufacturing Company

1001 West Second Street

P. O. Box 306

Seymour, IN 47274

Phone: 812-522-1121

Fax: 812-522-6060

September 13, 1996

United States Nuclear Regulatory Commission
801 Warrenville Rd
Lisle, IL 60532-4351


Dear Sir:

On August 21, 1996 all the assets of North American Wood Products were purchased by NAWP Acquisition Corp d/b/a Seymour Particleboard Mfg.

The nuclear guage covered by our NRC Material License No. 13-14807-01 will no longer be in use effective September 20, 1996. We are shutting down the portion of our operation that uses that device.

If you have any questions, please contact me.

Sincerely,



Stephan Pinsly
President

Illumination
FEE EXEMPT

RECEIVED
SEP 17 1996
REGION III

Pm: 9-13-96

SEP 17 1996

301836

DATE: 9-17-96

CORRESPONDENCE CLARIFICATION SHEET

REVIEWER: John Madera
LICENSEE: NORTH AMERICAN
LICENSE NUMBER: 13-14807-01

The following correspondence has been received from the above licensee and it is not clear what action(s) is(are) required: Please review this correspondence and indicate which of the following applies, and please return to Debbie Hersey, as soon as possible.

☐ Additional Information to Control No. _____
Process in as a new action, additional information, and no fee required.

☐ Process as new licensing action. Review has already been started on Control No. _____ and this information cannot be combined with current in-house action.

☐ Can be combined with Control No. _____. Review has not been started.

☒ Appears to be a(n) Termination Request - Process

☐ Appears to be information for the license file - file it.

☐ Licensee is adding Nuclear Pharmacists.
Amendment is necessary _____. Amendment is not necessary _____.
(Information for license file)

☐ Licensee is adding authorized users.
A check is included _____. No check is included _____.
Amendment is necessary _____. Amendment is not necessary _____.
(Information for the license file)

☒ Other: _____

Thank You For Your Help!!!

02/02/95

OCT 21 1996

J. David Swain
Seymour Particleboard
Manufacturing Co.
1001 West Second Street
P.O. Box 306
Seymour, IN 47274

Dear Mr. Swain:

Enclosed is Amendment No. 07 which terminates your NRC License Number 13-14807-01 in accordance with your request.

If you have any questions or require clarification on any of the information stated above, you may contact us at (630) 829-9887.

Sincerely,

Original Signed By
Michael F. Weber
Nuclear Materials Licensing Branch

License No.: 13-14807-01
Docket No.: 030-08079

Enclosure: Amendment No. 07

cc: Stephan Pinsly, President

DOCUMENT NAME: M:\03008079.TR6

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	DNMS/RIII	C							
NAME	MWEBER:jaw								
DATE	10/21/96								

OFFICIAL RECORD COPY

301826



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
801 WARRENVILLE ROAD
LISLE, ILLINOIS 60532-4351

September 19, 1996

J. David Swain
Executive Vice President, RSO
North American Wood Products, Inc.
d/b/a Swain Industries
P. O. Box 306
Seymour, IN 47274

SUBJECT: ACKNOWLEDGEMENT OF CORRESPONDENCE
(Letter Dated 09/13/96)

Dear Licensee:

In response to your request, we have completed the initial processing, which is an administrative review of your application for a(n):

☐ New License ☐ Amendment ☐ Renewal
☒ Termination ☐ Auth User (Amendment not required)
☐ Other _____

No administrative deficiencies were identified during this initial review. However, it should be noted that a technical review may identify omissions in the submitted information.

It appears that your request is routine (see 1-3 below, as applicable).

1. New and amendment actions are normally processed within 90 days, unless we find major deficiencies, or policy issues requiring central program office assistance.
2. Renewal actions are normally processed within 180 days, however, under timely filing (before expiration), you may continue to operate under your existing license.
3. Termination actions are normally processed within 90 days, unless confirmatory surveys following decontamination/decommissioning activities are involved.

A copy of your correspondence has been forwarded to our Licensing Fee and Debt Collection Branch (301/415-6097) for approval of the fee category and amount, if required.

If you have a compelling safety or business-related reason for requesting expedited review, please contact the Materials Licensing Branch at (630) 829-9887. We will try to complete your request as soon as practicable. Any correspondence about this request should reference the control number.

Nuclear Materials Support Branch

Mail Control No. 301836
License No. 13-14807-01



SWAIN INDUSTRIES, INC.

MANUFACTURERS OF FLAKE BOARD PRODUCTS
DIVISION OF NORTH AMERICAN WOOD PRODUCTS, INC.
SEYMOUR AND EVANSTON, IN

Trimwood

TELEPHONE (812) 522-1121

FAX (812) 522-6060

1001 WEST SECOND STREET

P.O. BOX 306

SEYMOUR, INDIANA 47274

United States Nuclear Regulatory Commission
Region III
801 Warrenville Road
Lisle, IL 60532-4351

October 17, 1996

Ref: Control # 301836

Dear sirs:

The purpose of this letter is to request termination of our NRC license # 13-14807-01.

Our only gage was removed from the premises by the manufacturer, Ohmart, on Tuesday, 10/15/96. Copies of the Field Service Report, the TM&E Report, the Returned-Source Package Radiation Field Survey, and the bill of lading are enclosed.

Thank you for your assistance.

Sincerely,

J. David Swain
J. David Swain

RECEIVED
OCT 21 1996
REGION III

Pm: 10-17-96

OCT 21 1996

Ohmart

Field Service Report

Phone 513-272-0131
Fax 513-272-0133
Emergencies 513-272-0135

4241 Allendorf Drive - Cincinnati, OH - 45209

Field Service # IN96 120-3192

C.O. # 30885

Service P.O. # FG001

Visit Date(s) 10-15-96

Page 1 of 1

IN ADDRESS

SERVICE LOCATION

Seymour Particleboard

1001 W. 2ND ST.

Seymour, IN.

47274

Radiation Safety Training

Yes No Initial

Leak Test

Radiation Survey

Visit Purpose

Disposal

Revisit

N

Customer Contact

Dave Swain

Calibration Data

N/A

Phone #

(812) 522-1121

Assisted in removing one HM-8 type source holder from service. 100mCi, Cs-137 S/N- 61719 Source holder was banded on skid for transfer to Ohmart. T.I = 0.2 Survey, Leak Test, Gross contamination performed. Source holder labeled, Bill of Lading filled out. MRA # 6016

The Ohmart Corporation believes strongly in the safe use of radioactive material by applying the ALARA principles. No comments written or verbal by any Ohmart employee should be considered as a deviation from that philosophy nor as permission to violate any regulation or condition of your license. Compliance with your license requirements and the appropriate regulations is your responsibility.

Customer Signature

X [Signature]

Service Representative

[Signature]

TIME, MATERIAL & EXPENSE REPORT

FIELD SERVICE# IN 46-120-3142
SHOP ORDER# 30885
SERVICE P.O.# FC-001

SERVICE	LOCATION
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

Seymour Particle Board
1001 W. 2nd St.
Seymour, IN.

VOICE	ADDRESS
1	1000
2	1000
3	1000
4	1000
5	1000
6	1000
7	1000
8	1000
9	1000
10	1000
11	1000
12	1000
13	1000
14	1000
15	1000
16	1000
17	1000
18	1000
19	1000
20	1000
21	1000
22	1000
23	1000
24	1000
25	1000
26	1000
27	1000
28	1000
29	1000
30	1000
31	1000
32	1000
33	1000
34	1000
35	1000
36	1000
37	1000
38	1000
39	1000
40	1000
41	1000
42	1000
43	1000
44	1000
45	1000
46	1000
47	1000
48	1000
49	1000
50	1000
51	1000
52	1000
53	1000
54	1000
55	1000
56	1000
57	1000
58	1000
59	1000
60	1000
61	1000
62	1000
63	1000
64	1000
65	1000
66	1000
67	1000
68	1000
69	1000
70	1000
71	1000
72	1000
73	1000
74	1000
75	1000
76	1000
77	1000
78	1000
79	1000
80	1000
81	1000
82	1000
83	1000
84	1000
85	1000
86	1000
87	1000
88	1000
89	1000
90	1000
91	1000
92	1000
93	1000
94	1000
95	1000
96	1000
97	1000
98	1000
99	1000
100	1000

[illegible]

TOTAL	TRAVEL (REG)		229672
	TRAVEL (OVT)		229673
	TRAVEL (SUN)		229674
	SERVICE (REG)		229669
	SERVICE (OVT)		229670
	SERVICE (SUN)		229671
DISPOSAL FEES			
	SOURCE	\$	229677
	MCI CONTENT	\$	229678
SCHOOL FEES		\$	229679

Time & Materials Acknowledgement

Customer
Signature

Field Service Engineer _____

Approved By

Date _____

NO CHARGE

☐ Warranty ☐ Production ☐ Engineering ☐ Field Service ☐ Travel Delay ☐ Sales

DAY OF THE WEEK	SUN.	MON.	TUES	WED.	THURS.	FRI.	SAT.	TOTALS
DATE								
Car Allowance (mileage)								
Motel expense								
Meals (incl. tips) Breakfast								
Lunch								
Dinner								
Telephone								
Airport Parking								
Misc.								
Totals								

CASH	\$
AIRLINE	\$
AD	\$
MILEAGE	\$
EXPENDITURES + 15%	\$
FREIGHT	\$

CHARGE TO

☐ Customer ☐ Start up Pkg ☐ P.M.P. Visit

Vendor #

01-000-00-0409


01- -00-

CUSTOMER


F.S. # IN96-120-3192HIGHEST SURFACE FIELD
(SEE NOTE #3)30mR/HMRA # 6016TRANSPORT INDEX
(SEE NOTE #4)0.2SOURCE HOLDER(S) PACKED: ON SKID ☒IN BOX ☐SKID # 1

ECO NUMBER	BY	REVISION	DATE
1	JESSE	ADD NOTES: DELETE READINGS	10/08

SEE NOTES #1 & 2



SEE NOTES #1 & 2

30mR/H
(Below)

1# SO/CO# 30885
 SOURCE HOLDER LOCKED "OFF" yes
 SOURCE HOLDER MODEL CP8/HM-8
 SOURCE MAT'L 5-137
 SOURCE ACTIVITY 100 mCi (1mCi=0.037GBq)
 SOURCE SERIAL NO. 61719
 ORIGINAL SHIP DATE 5/71
 GROSS CONTAMINATION CHECKED yes
 LEAK TEST PERFORMED yes

2# SO/CO# 30885
 SOURCE HOLDER LOCKED "OFF" yes
 SOURCE HOLDER MODEL CP8/HM-8
 SOURCE MAT'L 5-137
 SOURCE ACTIVITY 100 mCi (1mCi=0.037GBq)
 SOURCE SERIAL NO. 61719
 ORIGINAL SHIP DATE 5/71
 GROSS CONTAMINATION CHECKED yes
 LEAK TEST PERFORMED yes

SURVEY METER:

Dosimeter
 MFR 3500
 MODEL 31-1291
 SERIAL NO. 12/22/95
 LAST CALIBRATION DATE 10
 SURVEYED BY J. HARRIS

3# SO/CO# 30885
 SOURCE HOLDER LOCKED "OFF" yes
 SOURCE HOLDER MODEL CP8/HM-8
 SOURCE MAT'L 5-137
 SOURCE ACTIVITY 100 mCi (1mCi=0.037GBq)
 SOURCE SERIAL NO. 61719
 ORIGINAL SHIP DATE 5/71
 GROSS CONTAMINATION CHECKED yes
 LEAK TEST PERFORMED yes

4# SO/CO# 30885
 SOURCE HOLDER LOCKED "OFF" yes
 SOURCE HOLDER MODEL CP8/HM-8
 SOURCE MAT'L 5-137
 SOURCE ACTIVITY 100 mCi (1mCi=0.037GBq)
 SOURCE SERIAL NO. 61719
 ORIGINAL SHIP DATE 5/71
 GROSS CONTAMINATION CHECKED yes
 LEAK TEST PERFORMED yes


LABELING:

DOT TYPE 7A PACKAGE yes
 OVERPACK no
 HAZARDOUS MATERIAL IDENTIFICATION UN2974
 WHITE I 30 mR/hr SURFACE (SURFACE < 0.5mR/hr)
 YELLOW II 30 mR/hr SURFACE (0.5 < SURFACE < 50mR/hr)
 REPORTABLE QUANTITY (RQ) no

NOTES:

- 1) INDICATE POSITION OF SOURCE HOLDER ON SKID OR IN BOX.
- 2) CHECK EACH SOURCE HOLDER OR EACH SIDE OF BOX FOR THE HIGHEST SURFACE FIELD. INDICATE WHERE THIS FIELD IS LOCATED BY DRAWING AN ARROW (→).
- 3) WRITE THE HIGHEST SURFACE FIELD READING IN THE FIELD AT THE TOP OF THIS FORM.
- 4) SURVEY AT 1 METER (39.4 INCHES) FROM THE SURFACE/EDGE OF THE PALLET/BOX AND PAY PARTICULAR ATTENTION TO THE AREA OUT FROM THE HIGHEST SURFACE FIELD. THE TRANSPORT INDEX IS THE DIMENSIONLESS NUMBER (ROUNDED UP TO THE FIRST DECIMAL PLACE) EXPRESSING THE MAXIMUM RADIATION LEVEL IN MILLIREM PER HOUR AT ONE METER (3.3 FEET) FROM THE EXTERNAL SURFACE OF THE PACKAGE.

USER NAME Seymour Particklaxer
 USER ADDRESS 1001 W. 2nd ST
Seymour, IN.
 P.O.# FG 001
 CONTACT Davin Swain
 TELEPHONE (812) 522-1121
Floyd Green
(812) 529-8171

OHMART IDENTIFICATION NUMBER: 56058
 THE OHMART CORPORATION
 4741 ALLENDORF DRIVE, CHICAGO, ILL. 60630 U.S.A.
 RETURNED-SOURCE PACKAGE
 RADIATION FIELD SURVEY

THIS DOCUMENT INCLUDES INFORMATION WHICH IS PROPRIETARY TO THE OHMART CORPORATION. NEITHER THIS DOCUMENT NOR THE INFORMATION DISCLOSED HEREIN SHALL BE USED OR DISCLOSED TO OTHERS FOR MANUFACTURING OR ANY OTHER PURPOSE EXCEPT SPECIFICALLY AUTHORIZED BY WRITING BY THE OHMART CORPORATION. THIS DOES NOT APPLY TO INFORMATION FURNISHED BY VENDORS OR OTHERS OUTSIDE THE OHMART CORPORATION.

STRAIGHT BILL OF LADING — SHORT FORM

ORIGINAL — NOT NEGOTIABLE

(Name of Carrier)

RECEIVED, subject to the classifications and tariffs in effect on the date of the issue of this Bill of Lading

at 19 From

The property described below, in apparent good order, except as noted (contents and condition of contents of packages unknown), marked, consigned, and destined as indicated below, which said carrier agrees to carry to its usual place of delivery at said destination, if on its route, otherwise to deliver to another carrier on the route to said destination. It is mutually agreed, as to each carrier of all or any of said property over all or any portion of said route to destination, and as to each party at any time interested in all or any of said property, that every service to be performed hereunder shall be subject to all the terms and conditions of the Uniform Domestic bill of Lading set forth (1) in Official, Southern, Western and Illinois Freight Classifications in effect on the date hereof, if this is a rail or a rail water shipment, or (2) in the applicable motor carrier classification or tariff if this is a motor carrier shipment.

Shipper hereby certifies that he is familiar with all the terms and conditions of the said bill of lading, including those on the back thereof, set forth in the classification or tariff which governs the transportation of this shipment, and the said terms and conditions are hereby agreed to by the shipper and accepted for himself and his assigns.

Consigned to The Ohmart Corporation

Destination 4241 Allendorf Drive

Cincinnati

State Ohio

Zip Code 45209

Route

No. Packages	H/M	Kind of Packages, Description of Articles, Special Marks and Exceptions	Weight (sub to Car.)	Principal Radioactive Contents	Activity of Contents	Transport Index	Type Label
1		<p>RADIOACTIVE MATERIAL SPECIAL FORM N.O.S., 7, (Cs-137) UN 2974</p> <p>RADIOACTIVE MATERIAL N.O.S., 7, () UN 2982</p> <p>DO NOT PLACE UNDEVELOPED FILM WITHIN 15 FEET OF THE CONTAINER</p> <p>RADIOACTIVE MATERIAL, NOI, Item No. 164900 (The agreed or declared value of the property is hereby specifically stated by the shipper to be not exceeding 40 cents per pound)</p> <p>For ion chamber detectors only</p> <p>ARGON NON-FLAMMABLE GAS, 2.2, UN-1006 (DOT E 8-72)</p> <p>IN METAL CYLINDERS (ITEM NO. 85880)</p> <p>This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation, according to applicable regulations of the Department of Transportation.</p> <p>Emergency Contact (513) 272-0135</p>	150 #	Cs-137	100mCi (3.7GBq)	2	yellow II

SHIPPER'S REF NO. PO # FG001

MATERIAL RETURN AUTHORIZATION NO. 6016

If charges are to be prepaid, write or stamp here, "TO BE PREPAID"

TO BE PREPAID

NAME OF SHIPPER

Seymour Particle board

PERMIT POST OFFICE ADDRESS OF SHIPPER

1001 W. 2nd St.

Seymour, TN. 47274

RECEIVED BY

DATE