

NOV 6 1984


MEMORANDUM FOR: Jerome J. Blake, Chief, Materials and Processes Section
Engineering Branch, Division of Reactor Safety

FROM: William P. Ang, Mechanical Engineering Inspector, Materials
and Processes Section

SUBJECT: SHEARON HARRIS ALLEGATIONS (CASE NO. RII-84-A-0143)

On November 1, 1984, I participated in an interview with Mr. Chan Van Vo regarding his allegations. Present at the interview were Mr. L. Robinson, of the Office of Investigations (OI), Mr. R. Guild, who was representing Mr. Vo and GAP, Ms. B. Levitas, a GAP volunteer, and K. Weller, a court reporter.

Details of the interview are contained in the court reporter's transcript. Copies of various related documentation presented by Mr. Vo are in the possession of OI. Briefly, Mr. Vo discussed his concerns regarding pipe support material, inspection and records. Mr. Vo also discussed his concern regarding cold springing of piping to an SG feed pump. Mr. Vo also discussed his concerns regarding the QA program in general. Mr. Vo was assured that the NRC would investigate his concerns.


William P. Ang

RII

B508230134 850814
PDR FOIA
GUILD85-173 PDR

WPAng:bh
11/14/84

A105

A105



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

NOV 6 1984


MEMORANDUM FOR: Jerome J. Blake, Chief, Materials and Processes Section
Engineering Branch, Division of Reactor Safety

FROM: William P. Ang, Mechanical Engineering Inspector, Materials
and Processes Section

SUBJECT: SHEARON HARRIS ALLEGATIONS (CASE NO. RII-84-A-0143)

On November 1, 1984, I participated in an interview with Mr. Chan Van Vo regarding his allegations. Present at the interview were Mr. L. Robinson, of the Office of Investigations (OI), Mr. R. Guild, who was representing Mr. Vo and GAP, Ms. B. Levitas, a GAP volunteer, and K. Weller, a court reporter.

Details of the interview are contained in the court reporter's transcript. Copies of various related documentation presented by Mr. Vo are in the possession of OI. Briefly, Mr. Vo discussed his concerns regarding pipe support material, inspection and records. Mr. Vo also discussed his concern regarding cold springing of piping to a SG feed pump. Mr. Vo also discussed his concerns regarding the QA program in general. Mr. Vo was assured that the NRC would investigate his concerns.


William P. Ang

A64

A64