

ENCLOSURE

NOTICE OF VIOLATION

Carolina Power and Light Company  
Brunswick 1 and 2

Docket Nos. 50-325 and 50-324  
License Nos. DPR-71 and DPR-62

The following violations were identified during an inspection conducted on July 1-31, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

1. 10 CFR 50 Appendix B, Criterion XVI, as implemented by FSAR Section 17.2.16, Corrective Action, requires measures be established to assure that conditions adverse to quality (i.e., deficiencies) are promptly identified and corrected. Technical Specification 6.8.1.c requires that the licensee maintain and implement procedures specified in Reg. Guide 1.33, November 1972. Item "E" of the guide requires that procedures for correcting abnormal, offnormal or alarm conditions be implemented.

Contrary to the above, a condition adverse to quality was not adequately corrected in that most annunciator procedures which required changes, necessitated by the introduction of Emergency Operating and Abnormal Operating Procedures and the elimination of the Emergency Instructions, were not updated and corrected or an alternate means adequately provided to clarify reference discrepancies contained in the procedures.

This is a Severity Level V violation (Supplement I).

2. 10 CFR 50 Appendix B, Criterion V, as implemented by FSAR Section 17.2.5, requires activities affecting quality be accomplished in accordance with drawings.

Contrary to the above, activities affecting quality were not accomplished in accordance with drawings in that control rod drive hydraulic control units on Unit 2 were not installed per drawing. Four units were found with loose bolting and one unit had 2 out of 4 rack-support-to-foundation bolts missing.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

8508280434 850813  
PDR ADOCK 05000324  
Q PDR

Carolina Power and Light Company  
Brunswick Units 1 and 2

2

Docket Nos. 50-325 and 50-324  
License Nos. DPR-71 and DPR-62

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: AUG 13 1985