



5501 N. State Route 2
Oak Harbor, OH 43449

419-249-2300
FAX: 419-321-8337

John K. Wood
Vice President - Nuclear
Davis-Besse

Docket Number 50-346

License Number NPF-3

Serial Number 2437

February 4, 1997

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555-0001

Subject: Semiannual Fitness-For-Duty Report July - December, 1996

Ladies and Gentlemen:

Pursuant to 10 CFR 26.71(d) "Record Keeping Requirements", Toledo Edison submits its semiannual Fitness-For-Duty (FFD) report for the period of July - December 1996 for the Davis-Besse Nuclear Power Station, Unit 1.

Attachment 1 provides Toledo Edison's FFD Program Performance Data. Attachment 2 provides a summary of management actions taken by Toledo Edison based on positive FFD testing results, presumptive positives, and a list of FFD event reports submitted by Toledo Edison.

Should you have any questions or require additional information, please contact Mr. James L. Freels, Manager - Regulatory Affairs, at (419) 321-8466.

Sincerely,

ASC

Attachments

110067

cc: A. G. Hansen, NRC Project Manager
A. B. Beach, Regional Administrator, NRC Region III
S. Stasek, DB-1 Senior Resident Inspector
Utility Radiological Safety Board

9702120094 970204
PDR ADDOCK 05000346
R PDR

A021

Docket Number 50-346
License Number NPF-3
Serial Number 2437

Toledo Edison

Fitness-For-Duty Report

July - December 1996

Docket Number 50-346
 License Number NPF - 3
 Serial Number 2437
 Attachment 1

**Fitness for Duty Program
 Performance Data
 Personnel Subject to 10CFR 26**

 Toledo Edison
 Company

 Davis-Besse
 Location

 J. L. Freels, Manager - Regulatory Affairs
 Contact Name

 December 31, 1996
 6 Months Ending

 (419) 321-8466
 Phone

 Cutoffs: Screen/Confirmation (ng/ml)

 Appendix A to 10CFR 26

Marijuana 50/15
 Cocaine 300/150
 Opiates 300/300

Amphetamines 1000/500
 Phencyclidine 25/25
 Alcohol (%BAC) 0.04

Testing Results	Licensee Employees		Long-Term Contractor Personnel		Short-Term Contractor Personnel	
Average Number with Unescorted Access	805		0		88	
Categories	# Tested	# Positive	# Tested	# Positive	# Tested	# Positive
Pre-Access	15	0			12	0
Post Accident	0	0			0	0
Observed Behavior	0	0			0	0
Random	254	0			6	0
Follow-up	7	0			0	0
Other	90	0			0	0
Total	366	0			18	0/0

Breakdown of Confirmed Positive Tests for Specific Substances

	Marijuana	Cocaine	Opiates	Amphetamines	Phencyclidine	Alcohol	Refusal to test	
Licensee Employees	0	0	0	0	0	0	0	
Long-Term Contractors	0	0	0	0	0	0	0	
Short-Term Contractors	0	0	0	0	0	0	1	
Total	0	0	0	0	0	0	1	1

Docket Number 50-346
License Number NPF-3
Serial Number 2437
Attachment 2

TOLEDO EDISON MANAGEMENT ACTIONS
RELATING TO
FITNESS-FOR-DUTY

	Toledo Edison Personnel	Contractor Personnel
Referred to EAP	0	NA
Management Sanctions	0	1

Toledo Edison does not perform onsite initial drug screening tests; therefore there are no unconfirmed positive results on which to base management actions.

TOLEDO EDISON
FITNESS-FOR-DUTY
REPORTS

There were no Fitness-For-Duty reports submitted during this reporting period (July - December 1996).