

## UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE JULY 15, 1985

REPORT MONTH JUNE, 1985

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN

ENGINEER-IN-CHARGE

LICENSING SECTION

GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	(1)	(HOURS)	(2)	REACTOR (3)	REPORT #	(4)	(5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
1	850601	S	720.0	C	1	NA	RC	FUELXX	SHUTDOWN FOR IYS SIXTH REFUELING, MAINTENANCE, AND MAJOR MODIFICATION OUTAGE.
			720.0						

(1)

(2)

(3)

(4)

F - FORCED

S - SCHEDULED

REASON

A - EQUIPMENT FAILURE (EXPLAIN)

B - MAINTENANCE OR TEST

C - REFUELING

D - REGULATORY RESTRICTION

E - OPERATOR TRAINING + LICENSE EXAMINATION

F - ADMINISTRATIVE

G - OPERATIONAL ERROR (EXPLAIN)

H - OTHER (EXPLAIN)

METHOD

1 - MANUAL

2 - MANUAL SCRAM.

3 - AUTOMATIC SCRAM.

4 - OTHER (EXPLAIN)

EXHIBIT G - INSTRUCTIONS

FOR PREPARATION OF DATA

ENTRY SHEETS FOR LICENSEE

EVENT REPORT (LER)

FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

8509030015 850823  
PDR ADOCK 05000277  
PDR  
R