

**AMOT
CONTROLS**

AMOT Controls Corporation

401 First Street, Richmond, California 94801-2906, Tel: (510) 236-8300 Fax: (510) 234-9950

November 15, 1996

Document Control Desk**U.S. Nuclear Regulatory Commission****Washington, DC 20555-0001****Attn: Thomas Greene, NRR/PECB****Mail Stop: 0-11E4**

Subject: Request for Technical Review of a Draft Revision to Information
Notice 91-85

Failure of Thermostatic Control Valves


Dear Mr. Greene,

Thank you for the opportunity to review the revision to Information Notice 91-85.

May I suggest inclusion of the following on page 3 paragraph 1, after the
sentence stating the normal service life of 6-10 years. "Excessive temperatures,
chemical, electrolytic or cavitation attack will shorten the service life elements
and seats."

Thank for your attention to this important issue.

Sincerely,



Mark Woltering
Executive Vice President

217088

9611220062 961115
PDR I&E
NOTICE91-085 PDR

NRC FILE CENTER COPY

96-151

1601 1/0

ID+R-5
Info Ltr